

DATE: 4, 7, 81

T30S R9W
1/4 S32
55
T31S R9W

Condition Report Only
Not Found
 Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewal #'s 94, 95 ^{T30-9} 124-148 T31-9

Monument(s) Found: (Condition and Source) From renewal #95

a 2 1/2 inch DCSO brass cap on a 1 inch iron pipe is firmly set and protruding 6 inches from the ground. Cap is marked: COUNT SURVEYORS OFFICE

From 1893 resurvey a stone measuring 14x10x4 inches

is deposited on top of ground and set on the East side of the brass cap monument.

The stone is marked 1/4 on its top side (record 1/4 on N face) A steel fencepost protrudes 36 inches from the ground on the west side of the brass cap monument.

Accessories Found: (Condition and Source) Possible remains of original Southeast 18 inch Fir are found near record bearing and distance. No evidence of the other original bearing tree is found. From

the 1893 retracement a Fir 18 ins. diam. is now a burned D. Fir snag 18 inch D.B.H. ^{approx} 35 feet tall bears S34°E, 17 1/2 feet distant face measurement (record S33 3/4°E,

#127 T30-9 ✓
#165 T31-9 ✓

17 1/2 feet dist.); tree has good evidence of burned
blazes no scribing visible. A Fir, 30 ins. diam. now
the remains of a large burned and rotted Fir stump bears
N 14 1/4° W 84 1/2 feet distant (as per record) no blazes
(cont'd p 2)

RENEWAL

Monument Set: (Procedure and Description) monument location
is accepted as found.

New Accessories: ^{A boat spike in} (Description) a 12 inch diameter
^{burled fir stump}
12 inch tall bears N 06 3/4° W, 9 1/2 feet distant; the boat
spike driven into the top of said stump is stamped
B 0 2. ^{A spike in} a D. Fir stump 20 inches in diameter and
21 inches tall bears S 59 1/2° W, 42 1/2 feet distant;
the boat spike driven into the top of said stump is stamped B 0 1.
(cont'd p 2)

Location and Comments: _____
_____ Compass Declination
_____ Agency
_____ Party Chief
_____ Notekeeper
_____ Witnesses

DATE: 4/7/81

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

T30S R9W

$\frac{1}{4}$ $\frac{S32}{S5}$

T31S R9W

Previous Renewal #'s 94, 95

Monument(s) Found: (Condition and Source) _____

Accessories Found: (Condition and Source) (cont'd from pg 1)

or scribing apparent (rotted away). From renewal

94 two trees are found. A Doug. Fir, 22 inches now

a dead 26 inch D.B.H. D Fir bears S 10°W, 34[±] feet distant

(record S 12°W, 34[±] ft) tree has burned open blaze

with no legible scribing. A Doug, Fir 22 inches now

a 38 inch D.B.H, D. fir dead bears N 25°E, 13[±] ft.

distant (as per record) an opened blaze has the scribing
1/4 S 32 visible.

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description) (cont'd from pg 1)

a 8 inch D.B.H. Madrone bears N 16° W, 81⁹ feet
distant and is bark scribed 1/4 S 32 CS BT.

All accessories are tagged with DCSO BT tags.

Location and Comments: 19° E Compass Declination

DCSO Agency

Deputy Stephen John Fluse Party Chief

Stephen John Fluse Notekeeper

TERRIE PLOWFF Witnesses

KAREN MOSELY

OK
[Signature]