

DATE: 4-28-81

T305 RIW

1/4

S15 | S14

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 3, 151, 176

Monument(s) Found: (Condition and Source) From renewal #176

a 2 1/2 inch brass cap on a 2 inch iron pipe protrudes 3 inches from a rough pile of stone and is marked as below.

From renewal #151 a 2 1/2 inch T305 RIW

brass cap on a 1 inch iron pipe 1/4 S15 | S14

leans north and protrudes 7 inches from ground. As recorded in renewal RLS 866 1978

#151 a stone measuring 14 x 11 x 6 inches rests on the north side

of this monument. The cap is marked DOUGLAS CO. SURVEYOR

This cap bears S01°E, 14 3/4 feet distant from cap set in renewal #176 (as per record) T305 RIW S15 | S14

Accessories Found: (Condition and Source) 1/4 1976

Original corner and accessories

have been lost since before 1920, no evidence is

found. A survey by RLS Rupert in 1978 indicates

the corner location as established in renewal #3 and perpetuated in renewal #151 is incorrect; bearing trees for

this position are <sup>now</sup> referenced to 1978 corner and therefore recorded in this renewal as new accessories. From renewal

#216 X

#176 a 19" D. fir now a 2 inch d.b.h. D. fir bears N 86 $\frac{1}{2}$ ° W.  
28 $\frac{6}{10}$  ft. distant (as per record) and is scribed "1/4 S15 BT" on a  
partially healed double blaze. A 10" Madrone now an 11 inch d.b.h.  
Madrone bears N 28° E, 17 $\frac{2}{10}$  ft distant (as per record)  
and is scribed "1/4 S14 BT" on an unhealed double blaze.

RENEWAL

Monument Set: (Procedure and Description) 1978 corner  
set by Rupert is accepted as found.

As recorded in "Monuments Found"  
New Accessories: (Description) position of brass cap from  
renewal #151 is referenced out, the cap is re-  
moved and replaced by a 5/8 inch by 30 inch long iron  
rod with an aluminum cap marked DOUGLAS CO. SURVEYOR.  
Stone on north side of brass cap from renewal #151 is not disturbed  
The following accessories have only bearing and  
distances to the 1978 corner recorded. All blazes and

Location and Comments:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

DATE: 4.28.81

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

T305 RIW

1/4

S15 | S14 cont'd

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

New accessories cont'd from pg 1

~~Accessories Found:~~ (Condition and Source) scribing face 1978

corner reasonably well, except where noted. From

renewal #3 two trees: A Yellow Pine 42" now a rotted

60 inch diam. 48 inch tall pine stump bears

S 74° E, 111<sup>g</sup> feet distant and has the scribing

1/4 S BT visible on an opened blaze. And

a Cedar 30" now a fallen 30 inch dbh. Cedar bears

S81°W, 141<sup>±</sup> feet distant and has a possible burned  
blaze facing corner. From renewal #151 two trees:  
A 5" p. fir now a 5 inch d.b.h. p. fir bears S33°E,  
24<sup>±</sup> feet distant and has a partially healed  
Contd below

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories: (Description) single blaze with the  
scribing CS BT visible. A 6" p. fir now a 7 inch d.b.h.  
p. fir bears S28 1/2°W, 9<sup>±</sup> feet distant and is scribed  
1/4 S15 CS BT on a partially healed single blaze  
facing south 36° East. All listed new accessories are  
tagged with DCSO bearing tree tags marked with  
bearing and distances as here recorded.

Location and Comments: \_\_\_\_\_ 19°E Compass Declination

\_\_\_\_\_ DCSO Agency  
Deputy Stephen John Flouse Party Chief  
Stephen John Flouse Notekeeper  
\_\_\_\_\_ KAREN MOSLEY Witnesses  
TERRIE PLOWFF  
\_\_\_\_\_