

DATE: 4/29/81

T295 R&W

E 1/16 S17  
S20

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s none recorded

Monument(s) Found: (Condition and Source) A 5/8 inch iron rod with an aluminum cap protrudes 3 inches from the ground and is firmly set. The aluminum cap is marked as follows:

DOUGLAS CO. SURVEYOR

1979

E 1/16 S17  
S20

The original monument for this corner as recorded in PCSO survey RM 2-20 was searched for and not found. sewerline excavation in area may have caused loss of this 3/4 inch iron rod.

Accessories Found: (Condition and Source) An original 15" R. fir now a 23 inch d.b.h. Douglas fir bears N 61° E, 31° feet distant (as per record) and has a healed double blaze with no scribing visible. An original 6" R. fir now a 16 inch d.b.h. Douglas fir bears S 70° E, 43<sup>2</sup> feet distant (as per record) and has a healed single blaze with no scribing visible. Both bearing trees are

✓

es. 6/19-58

Page 1 of 1 C  
per 413 sh.

tagged with BLM location tags and PCSO bearing  
tree tags correctly marked and dated 5.29.79

RENEWAL

Monument Set: (Procedure and Description) Monument location  
is accepted.

New Accessories: (Description)

Location and Comments: 19°E Compass Declination

PCSO Agency

Deputy Stephen John Fluso Party Chief

Stephen John Fluso Notekeeper

KAREN MOSLEY Witnesses

OK [Signature]

