

T29SR1W
S'116
S29!S28
RLS 934
1971

DATE: APRIL 30, 1981

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

2" IP., SET BY VICTOR MELIND, OLS 934, IN
1971, FIRMLY SET, PROJECTING 4" ABOVE
GROUND, WITH B.C. MARKED AS ABOVE.

Accessories Found: (Condition and Source) _____

5TS MARKED BY MELIND IN 1971;
A 12" W. FIR SNAG, S36°E, 12¹/₂ FT, WITH S.M.
"S'116 S28 BT" VISIBLE ON PARTLY HEALED
DOUBLE BLAZE

A 9" MAPLE SNAG, N37°W, 12³/₄ FT, WITH S.M.
"S'116 S29 BT" VISIBLE ON PARTLY HEALED
DOUBLE BLAZE. (REC. N31¹/₄°W)

WAYNE RODGERS, OLS 1004,

AND BT MARKED BY ~~HERGEN~~ IN 1979:

A 8" W. FIR, S 10° E, 27⁰⁷ FT. WITH S.M.

"S 116 S28 BT" AND BRASS WASHER STAMPED

"RS 1004" VISIBLE ON PARTLY HEALED DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) I MARKED NEW BT:

A 11" W. FIR, N 56° W, 17⁵ FT, SCRIBED

"S 116 S29 CS BT" ON DOUBLE BLAZE.

Location and Comments: 20° E Compass Declination

USFS Agency

LEONARD HERZSTEIN Party Chief

Notekeeper

JIM LANDRUM Witnesses

TOM WOLFORD

JOE MAGALLANEZ