

T29S R1W
S29
C.E.W.E
1/256
RLS 934
1971

DATE: MAY 4, 1981

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

2" I.P., FIRMLY SET, PROJECTING 4" ABOVE
GROUND, WITH B.C. MARKED AS ABOVE, SET
BY VICTOR MCLIND, OLS 934, IN 1971.

Accessories Found: (Condition and Source) _____

BTS MARKED BY MCLIND IN 1971:

A 18" D.FIK STUMP, N56°E, 10⁹ FT, WITH S.M.

"56 29" VISIBLE ON PARTLY HEALED DOUBLE
BLAZE.

A 14" I. CEDAR, S43½°W, 45⁶ FT, WITH S.M.

"1/256 S29 BT" VISIBLE ON PARTLY HEALED

DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

I MARK NEW BT:

A 7" D. FIR, N67°W, 30[±] FT, SCRIBED "1256529CSBT"
ON DOUBLE BLAZE.

Location and Comments:

22°E

Compass Declination

USFS

Agency

LEONARD HERZSTEIN

Party Chief

Notekeeper

JIM LANDRUM

Witnesses

TOM WOLFORD