



DATE: MAY 5, 1981

- Condition Report On
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 56

Monument(s) Found: (Condition and Source) 1" I.P., SET BY POWELL, DOUGLAS CO. SURVEYOR'S OFFICE IN 1969, FIRMLY SET, PROJECTING 12" ABOVE 3 FT. DIAMETER MOUND OF STONE, WITH BRASS CAP MARKED AS ABOVE.

Accessories Found: (Condition and Source) ORIGINAL BTS:

28" D. FIR STUMP, N50°E, 151⁴ FT., WITH NO MARKS VISIBLE.

42" D. FIR STUMP, S75°E, 112³ FT., WITH HEALED LOWER BLAZE.

21" I. CEDAR, S50°W, 47⁵ FT., WITH HEALED BLAZE

32" D. FIR STUMP, N81°W, 53⁵ FT., WITH HEALED BLAZE

#142 ✓

BTS MARKED BY POWELL IN 1969:

10" D. FIR, NS2¹/₂°E, 23²/₂ FT. (R&C, 23²/₂ FT.) WITH
HEALED DOUBLE BLAZE.

21" D. FIR, S55°E, 23⁴/₄ FT., WITH HEALED DOUBLE
BLAZE.

RENEWAL

Monument Set: (Procedure and Description)

SET GUARD POST 5 FT. NORTH OF B.C.
WITH USFS SIGNS #54-2 & #54-4 ATTACHED.

New Accessories: (Description)

I MARKED NEW BT:

6" D. FIR, NS9°W, 21⁶/₆ FT., SCRIBED.

"T29S R14 S20 CS BT" ON DOUBLE
BLAZE.

Location and Comments:

19°E

Compass Declination

USFS

Agency

LEONARD HERSTEIN

Party Chief

Notekeeper

JIM LANDRUM

Witnesses

TOM WOLFORD