

DATE: MAY 5 1981

TZ9S RIW
N¹/₁₆
S29! S28
RLS 934
1971

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s M42-39

Monument(s) Found: (Condition and Source) _____

2" IP, SET BY VICTOR MCELIND, RLS #934, IN
1971 ~~1970~~, FIRMLY SET, PROJECTING 6" ABOVE
GROUND, WITH BRASS CAP MARKED AS ABOVE.

Accessories Found: (Condition and Source) _____

BTS MARKED BY MCELIND IN 1971:
A 10" HALF-DEAD D. FIR, N42¹/₂°E, 6⁸ FT WITH
S.M. "N¹/₁₆ S28 BT" VISIBLE ON PARTLY HEALED
DOUBLE BLAZE.
A 14" D. FIR, S19°E, 15⁵ FT, WITH FRAGMENTARY
S.M. VISIBLE ON PARTLY HEALED DOUBLE BLAZE.

#137 ✓

Page _____ of _____
C. S. File No. 61/24-4 C

A 24" I. CEDAR SNAG, N 75 1/2° W (REC. S 89° W),
35 1/2 FT, WITH S.M. "N 1/16 S 29 BT" VISIBLE
ON PARTLY HEALED DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) _____

I ADD 3' MOUND OF STONE, WITH BRASS
CAP NOW FLUSH.

New Accessories: (Description) _____

I MARKED NEW BT:

A 17" D. FIR, N 27 1/2° W, 14 1/4 FT, SCRIBED "N 1/16
S 29 CS BT" ON DOUBLE BLAZE.

Location and Comments:

CORNER IS 100 FT.
SOUTH OF FRANCIS
CREEK ON STEEP
NORTH SLOPE.

17 1/2° E
USFS
LEONARD HERZSTEIN
JIM LANDRUM
TOM WOLFORD

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK 

#F137