

DATE: May 13, 1981

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

T.22S R5W

W $\frac{1}{16}$ $\frac{S25}{S36}$

Previous Renewal #'s none, established in survey M 80-54

Monument(s) Found: (Condition and Source) A $\frac{5}{8}$ inch diameter iron rod as set by Haines (see county survey records map M 80-54) is firmly set and protrudes 9 inches from the ground.

Accessories Found: (Condition and Source) An originally 40" D. Fir now a fir stump 40 inches in diameter and 30 inches tall with a metal weather protection cap bears $S^{51}E$, $62\frac{1}{2}$ feet distant (as per record) and has the scribing "BT" visible on a partially healed single blaze. An originally 14" D. Fir now a fallen 14 inch d.b.h., D. fir bears $S60^{\circ}W$, $32\frac{1}{2}$ feet distant

#165 X

(as per record) with the scribing "1/16 S36 BT" visible on a partially healed single blaze.

RENEWAL

Monument Set: (Procedure and Description) Haines monument is accepted as found.

New Accessories: (Description) A double trunk Maple with an average d.b.h. of 30 inches bears S 20 1/2° W, 61² feet distant and is bark scribed W 1/16 S36 CS BT. A 32 inch d.b.h., P. fir bears S 71 1/2° W, 36² feet distant and is scribed W 1/16 S36 CS BT on a double blaze. Bearing tree tags are placed on new B.T.'s and the fallen 14 inch fir B.T.

Location and Comments: 19°E Compass Declination
DCSO Agency
Deputy Stephen John Flouse Party Chief
Stephen John Flouse Notekeeper
KAREN MOSLEY Witnesses

(Ren. Request
By Woolley Logging)

OK 

21-2-51