

DATE: MAY 19 1981

T295RIW  
SW 1/16 . 529  
RLS 934  
1971

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s M42-39

Monument(s) Found: (Condition and Source) \_\_\_\_\_

2" I.P., SET BY VICTOR MCELIND, IN 1971, FIRMLY  
SET, PROJECTING 12" ABOVE GROUND, WITH  
BRASS CAP MARKED AS ABOVE.

Accessories Found: (Condition and Source) \_\_\_\_\_

BTs MARKED BY MCELIND IN 1971:  
A 24" D. FIR STUMP, N68 1/2° E, 34 FT, WITH  
S.M. "SW 1/16 529 BT" VISIBLE ON PARTLY  
HEAVED DOUBLE BLAZE.

A 8" W. FIR, N40° W, 11° FT WITH HEAVED  
DOUBLE BLAZE.

#138 ✓

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

I SCRIBE NEW BT:

A 5" D. FIR, S 11° W, 11<sup>6</sup> FT, MARKED "SW'16  
S29 CS BT" ON DOUBLE BLAZE.

Location and Comments: 35<sup>0</sup>E 35°E Compass Declination

USFS Agency

LEONARD HERZSTEIN Party Chief  
Notekeeper

JIM LANORUM Witnesses

TOM WOLFORD

OK 