

DATE: June 4, 1981

T 26 S

R
L
W

4525 | 530

R
S
W

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

T. 26 S
RANGE 6
T. 26 S

Previous Renewal #'s 18, 24 ~~#53~~ Monument Set: 1981

Monument(s) Found: (Condition and Source) From renewal

24 a 3/4 inch diam. iron rod protrudes 2 inches above ground and is firmly set. From renewal

*18 a stone measuring approx. 6 inches x 7 inches on its upper-most surface and there on marked 1/4 S, lies 1 inch below the surface of the ground and lies on the ^{nor} ~~sou~~theast edge of the above-mentioned iron rod monument.

Accessories Found: (Condition and Source) An original W. Oak

30 ins. diam. now a 41 inch d.b.b. White oak bears S 64 1/4° E, 741 2/3 feet distant (as per record) and has a healed blaze with no scribing visible. No evidence of original Y. oak found. From renewal

#24 a 10 inch W.O. now an 18 inch d.b.b. White oak bears S 66 1/2° E, 483 5/8 feet distant (as per

(T26-5) ✓
#150 / #182 (T26-6) X

record) and has a healed double blaze with
no scribing visible.

RENEWAL

Monument Set: (Procedure and Description) monuments
found are accepted.

New Accessories: (Description) Two property corner monuments
in the subdivision Saddle Butte Estates, 1st Addition. The
N.W. corner of lot 15 which is a $\frac{5}{8}$ inch x 30 inch iron rod
firmly set and protruding 4 inches from ground bears N $13\frac{1}{4}^{\circ}$ E,
423[±] feet distant. The S.W. corner of lot 16 which is a $\frac{5}{8}$ inch
iron rod with an aluminum cap marked "SHANER ENGINEERING" firmly
set and protruding 3 inches from the ground near the south edge of a
6 inch square, 6 foot tall cedar post bears N $56\frac{3}{4}^{\circ}$ E, 314[±] feet distant.
Location and Comments: 19^oF Compass Declination

	<u>MSO</u>	Agency
Deputy	<u>Stephen John Flaus</u>	Party Chief
	<u>Stephen John Flaus</u>	Notekeeper
	<u>TERRIE PLOWFF</u>	Witnesses

