

DATE: June 16, 1981

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

T275 R6W

1/4

516 | 515

Previous Renewal #'s 19

Monument(s) Found: (Condition and Source) A 3/4 inch diam

iron rod firmly set approximately 2 inches below the paved surface at the centerline of Calkins Road (County Road # 144); this is an unrecorded monument. A search is

made for the 1 inch iron pipe recorded in renewal #19 and the original monument, no evidence of these are found. This found

iron rod was set directly below a nail and ribbon as recorded in Bruce Rodgers survey recorded in county records map M83-3.

Accessories Found: (Condition and Source) A search is made

for evidence of the original bearing trees, no evidence is found. From renewal #19 a

30 inch now a 42 inch d.b.h. Black oak bears S02°E, 29° ft distant (face measurement) (record S. 2°E, 29 ft.), tree has evidence of a healed blaze, no scribing visible.

RENEWAL

Monument Set: (Procedure and Description) Found 3/4 inch iron rod is accepted as corner location because of agreement with pins found in Rodgers survey M83-3 (see monuments four) and face measurement agreement to bearing tree from renewal #19  
cont'd pg 2

New Accessories: (Description) A 3/4 inch iron pipe, firmly set and protruding 2 3/4 feet from the ground bears N65°E, 49.6 feet distant. An unmarked 6 inch d.b.h. Shore pine (P. contorta) bears S54°W, 102.9 feet distant. A power pole with a tag marked PPL B6267 PPL bears S75 1/2°W, 65.1 feet distant (cont'd pg 2)

Location and Comments:

19°E Compass Declination

DCSG Agency  
Deputy Stephen John Flouse Party Chief  
Stephen John Flouse Notekeeper  
Nebbie Stewart Witnesses

DATE: June 16, 1981

cont'd from pg 1  
T27S R6W  
1/4  
S16 | S15

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Accessories Found: (Condition and Source) \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

RENEWAL

Monument Set: (Procedure and Description) *(cont'd from p. 1)*

To the found iron rod monument is added a collar consisting of an 8 inch length of 6 inch diameter steel pipe this collar is tapped with an 8 inch diameter cast iron cap set flush with the paved road surface and marked "WATER"

New Accessories: (Description) <sup>*(cont'd from p. 1)*</sup> A 5 inch d.b.h. Sycamore, bark scribed  $\frac{1}{4}$  S 16 CS BT bears N 52° W, 98<sup>2</sup> feet distant. And a power pole marked "cop 2 Co" bears N 03° W, 17<sup>9</sup> feet distant. 334

Location and Comments: \_\_\_\_\_ 19°E Compass Declination

\_\_\_\_\_ DCSD Agency  
Deputy Stephen John Flawse Party Chief  
Stephen John Flawse Notekeeper  
Rebbie Stewart Witnesses

T 275 R 6W

1/4  
S16 | S15

5 inch dbh Sycamore  
bark scribed 1/4 S16 CSRT.

Power pole  
COP 2 CO

N 52° W  
98.2 ft.

N 03° W  
17.8 ft.

N 65° E  
49.6 ft.

3/4 inch iron pipe  
protruding 22 ft

power pole

S 75 1/2° W  
65.4 ft.

3/4 inch iron rod  
approx. 2" below road  
surface, 1/4 S16/S15

RPL  
B6267

S 54° W  
102.9 ft.

S 01° E  
29.4 ft (road measure)

B. oak  
42 inch dbh

6 inch d.b.h.  
Shore pine

(no scale)