

T225 R5W 1/4 58-9

DATE: 9/24/81

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 19, 30 AND CS FILE # 58/207

Monument(s) Found: (Condition and Source) FOUND FROM RENEWAL

#30 A 1" DIAMETER IRON PIPE WITH BRASS CAP STAMPED:  
" COUNTY SURVEYORS OFFICE "  
T225

$\frac{1}{4}$   
 S | S  
 8 | 9 → R5W TP  
 1957

CAP FOUND BADLY BENT AND LAYING FLUSH WITH GROUND.

\*NOTE: AS INDICATED IN RENEWALS 19 AND 30. THIS MON-  
UMENT SET WITH ORIGINAL BT AT S30°E (REC S35°E). WE  
ARE UNABLE TO FIND ANY INFORMATION TO CLARIFY THIS  
DISCREPANCY. WE AGREE WITH POSITION OF THE TRUE CORNER  
DETERMINED BY ROBERT DEAN CS FILE # 58/207 FROM WHICH  
THE MONUMENT SET BY BYRON RENEWAL #30 BEARS N43°E 2.93FT.

Accessories Found: (Condition and Source) FROM TRUE CORNER  
POSITION.

1) ORIGINAL W. OAK 8" NOW 48" DIAMETER WITH  
OPEN FACE SCRIBING "BT" VISIBLE BEARS S35°E 25.7 FT.

2) FROM RENEWAL #30 A 6" NOW 16" DIAMETER R. FIR  
WITH FAINT DOUBLE BLAZE BEARS N55 1/4°E 158.0 FT  
(REC N56°E 156.1 FT) FROM RENEWAL #30 POSITION.)

3) ORIGINAL 48" FIR BT NOT FOUND

4) CHINQUAPIN FROM RENEWAL #19 NOT FOUND.

RENEWAL

Monument Set: (Procedure and Description) AT TRUE CORNER

POSITION WE SET A 1" X 30" IRON PIPE WITH BRASS

CAP ATTACHED STAMPED: "DOUGLAS COUNTY SURVEYOR"

TZZS B5W

1458/29

1981

WE OBLITERATE MARKING ON CAP SET BY BYRON  
RENEWAL #30.

New Accessories: (Description) FROM RENEWAL #30 SEE

ACCESSORIES FOUND #23 (16" R. FIR) WE BLAZE AN

"X" IN BARK.

WE MARK: 1) A 9" DIAMETER FIR DOUBLE BLAZED SCRIBED.

1458 CS BT BEARS S 9 1/2° W, 100.9 FT.

2) A 16" FIR DOUBLE BLAZED SCRIBED 1458 CS BT BEARS  
S 40 1/2° W 202.7 FT.

Location and Comments:

19° E

Compass Declination

DOUGLAS CO. SURV. OFF.

Agency

LARRY

ED MONREAN DEP.

Party Chief

Jessie Plouff

Notekeeper

Witnesses

*OK [Signature]*