

T315 R2W WM

W 1/16 51
512

1978 OLS 536

DATE: APRIL 16, 1980

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 2" IRON PIPE

SET FIRMLY IN THE GROUND IN A MOUND OF
STONE WITH A 2 1/2" BRASS CAP ATTACHED.

BRASS CAP IS MARKED AS SHOWN ABOVE.

CORNER IS AT WLST BASE OF A 16" CEDAR.

Accessories Found: (Condition and Source) A 17" CEDAR

BEARS S 1°E, 22 1/2 FT, SCRIBING VISIBLE ON

DOUBLE UNHEALED BLAZES, "W 1/16 512 BT". A

BRASS WASHER, MARKED "LS 536" IS NAILED

FLUSH TO THE LOWER BLAZE. A 12" DOUG

FIR BEARS N 62°W, 10 1/2 FT. DOUBLE BLAZES

ARE PITCHED OVER. SCRIBING (FRAGMENTARY)

Page 1 of 1

✓ v.f.

S. File No. ~~5278~~

✓
 ✱ FD. OK 12-9-81
 WORK AT ROCK SITE
 DID NOT DISTURB COR.
 OR ACCESSORIES

C.S. 6/29-1

GP /

AND A BRASS WASHER (IN LOWER BLAZE) ARE
VISIBLE THROUGH THE PITCH. THE BLAZES ON
THE FIR DO NOT FACE THE CORNER. THEY FACE
N 80° E. ~~FACES~~ BLAZES ON CEDAR FACE
N 20° E, RATHER THAN THE CORNER.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A ⁵/₈" x 24" IRON ROD
WITH A 1 1/2" ALUM. CAP ATTACHED BEARS N 31° W,
942 ft. CAP IS MARKED "R.M."

A 5/8" IRON ROD (24" LONG) WITH A 1 1/2" ALUM.
CAP ATTACHED BEARS N 28° 30' E, 837 ft.

CAP IS MARKED "R.M." A METAL FENCE POST W/
PROPERTY BOUNDARY SIGN ATTACHED BEARS S 88° 30' W, 1280 ft.

Location and Comments: 17° E Compass Declination
U.S.F.S. Agency
DENNIS GAYLORD Party Chief
" " Notekeeper
LEONARD HERZSTEIN Witnesses

OK

4/24/80
?EF FOR ROCK SITE -
OR IN DANGER OF
BEING DESTROYED -
J.R.

C561/29-1

T315 R2W WM

DATE: APRIL 16, 1980

W 1/16 51
512

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

1978 OLS 536

Previous Renewal #'s M 65-79

Monument(s) Found: (Condition and Source) 2" IRON PIPE

SET FIRMLY IN THE GROUND IN A MOUND OF
STONE WITH A 2 1/2" BRASS CAP ATTACHED.
BRASS CAP IS MARKED AS SHOWN ABOVE.
CORNER IS AT WEST BASE OF A 16" CEDAR.

Accessories Found: (Condition and Source) A 17" CEDAR

BEARS S 1°E, 22 1/2 ft, SCRIBING VISIBLE ON
DOUBLE UNHEALED BLAZES, "W 1/16 512 BT". A
BRASS WASHER, MARKED "LS 536" IS NAILED
FLUSH TO THE LOWER BLAZE. A 12" DOUG
FIR BEARS N 62°W, 10 1/2 ft. DOUBLE BLAZES
ARE PITCHED OVER. SCRIBING (FRAGMENTARY)

X

✓ v.l.

AND A BRASS WASHER (IN LOWER BLAZE) ARE
VISIBLE THROUGH THE PITCH. THE BLAZES ON
THE FIR DO NOT FACE THE CORNER. THEY FACE
N 80° E. ~~FACES~~ BLAZES ON CEDAR FACE
N 20° E, RATHER THAN THE CORNER.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) A ⁵/₈" x 24" IRON ROD
WITH A 1 1/2" ALUM. CAP ATTACHED BEARS N 31° W,
94 ± FT. CAP IS MARKED "R.M."

A 5/8" IRON ROD (24" LONG) WITH A 1 1/2" ALUM.
CAP ATTACHED BEARS N 28° 30' E, 83.9 FT.

CAP IS MARKED "R.M." A METAL FENCE POST W/
PROPERTY BOUNDARY SIGN ATTACHED BEARS S 88° 30' W, 128.2 FT.

Location and Comments: 17° E Compass Declination
U.S. F.S. Agency
DENNIS GAYLORD Party Chief
" " Notekeeper
LEONARD HERZSTEIN Witnesses

OK [Signature]

4/24/80
REF. FOR ROCK SITE -
COR. IN DANGER OF
BEING DESTROYED -
J.R.