

T. 21 S. R. 11 W.

DATE: 10/13/81

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) _____

Original Corner Tree: 44" rotten D-Fir snag

Brass cap on 1 1/4" iron pipe, set by M-70-74 Survey, L.S. 497,
brs. S88°E, dist. 40', from tree, mkd.:

1/4

S29 | S28

1978

✓ 3/4" iron pipe set by PLS 239 (Survey M34-30), next to cap

Accessories Found: (Condition and Source) _____

✓ 13" D- Fir, brs. N48°E, dist. 130', scribing visible

✓ 24" D-Fir, brs. S9°W, dist. 165', scribing visible

50" D-Fir stump, brs. S3°E, dist. 3240'

#148 ✓

C. S. File No. 61/29-7

RENEWAL

Monument Set: (Procedure and Description)

New Accessories: (Description)

Location and Comments:

LOCATION: Travel
along Rd. #41, 1.1
miles past Otter Slough
to location poster on
Alder on West side of
road; they go West 400',
then South 445' to corner,
which lies 30' West of
ridge top.

20° E

U.S.F.S.

Emilio R. Alvarado
(same)

Colin Long

Compass Declination
Agency

Party Chief Doug. Co.
Notekeeper Deputy
Surveyor

Witnesses

OK