

T24S R2W

DATE: 10-14-81

S34 | S35  
TR 39

Condition Report Only  
Not Found  
 Renewed  
Unrecorded  
Surveyed In  
Referenced Out

Previous Renewal #'s RESURVEY, REN # 44

Monument(s) Found: (Condition and Source) FD. 1963 BRASS

<sup>BLM</sup>  
CAP PER RESURVEY FIRMLY SET, MARKED:

T24S R2W

S34 | S35  
TR 39

1963

Accessories Found: (Condition and Source)

FD. 9' NOW 14' PINE PER RESURVEY BEARS

N 34° E 34' (REC 35°) WITH WELL HEALED

SCAR. FD. ROTTED REMAINS OF 15" FIR

PER RESURVEY BEARS S 39° E 40'.

FD. 8" NOW 14" FIR PER REN # 44 BEARS

S 63° E 41' WITH WELL HEALED SCAR.

#111 ✓

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

6" FIR BEARS S54°W 5<sup>0</sup> FT SCRIBED

" S 34 CS BT" IN BARK.

11" FIR BEARS S83°W 24<sup>0</sup> SCRIBED =

"S34CSBT" IN DOUBLE BLAZE.

Location and Comments:

COR. LIES NORTH  
OF ROCK RD.

APPROX 220 FT

19°

ADCSO

Gregory E. Tinkler

GO

TERESA RULEY

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK  
JEM