

T 25 S R 4 W

DATE: NOVEMBER 16, 1981

$\frac{1}{4}$ $\frac{S 26}{S 35}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 1957 RESURVEY, #36 & #116

Monument(s) Found: (Condition and Source) AT QUARTER CORNER LOCATION

FOUND A BLM BRASS CAP APPROX 2 INCHES ABOVE GROUND, CAP IS
"T 25 S R 4 W"

STAMPED $\frac{1}{4}$ $\frac{S 26}{S 35}$ 1957 ALONG NORTHERLY SIDE OF CORNER

see below by # 12279

MONUMENT IS A 1" DIA. IRON PIPE WITH ATTACHED BRASS CAP STAMPED
"COUNTY SURVEYOR'S OFFICE"

T 25 S R 4 W THIS CAP ORIGINALLY SET IN RENEWAL
 $\frac{1}{4}$ $\frac{S 26}{S 35}$ 1957

NO. 36, PROTRUDES ABOUT 10 INCHES ABOVE GROUND.

Accessories Found: (Condition and Source) 1) (REN. #36) A CEDAR 10 NOW 24

INCH DIAMETER WITH WELL HEALED BLAZE BEARS N 31° E 254^B FEET (REC. PER

REN. #36 N 33° 47' E 255.01 FEET, PER 1957 RESURVEY N 29° 45' E 254^B FEET)

2) (1957 RESURVEY BT) A CEDAR 13 INCH DIAM. NOW A 6 FOOT HIGH 24 INCH

DIAM. STUMP WITH WELL HEALED BLAZE BEARS N 40^{3/4}° E 321³ FEET

(REC. N 39^{1/2}° E 335³ FEET)

3) (REN. NO. 116) A CEDAR 9 NOW 19 INCH DIAM. WITH HEALED BLAZE BEARS

#130 X

S 48 1/2° E 98 ± FEET (REG. S 50° E)

ALL OTHER TREES REPORTED DOWN IN PREVIOUS RENEWALS.

RENEWAL

Monument Set: (Procedure and Description) ~~HONOR~~ WE REMOVE THE COUNTY SURVEYOR BRASS CAP MONUMENT LEAVING THE B.L.M. MONUMENT AT CORNER POSITION AS FOUND.

New Accessories: (Description)

1) A D. FIR 8" DIA. DOUBLE BLAZED AND SCRIBED "1/4 S 26 CS BT" BEARS N 49 1/2° E 13 ± FEET.

2) A D. FIR 8" DIA ~~AND~~ SINGLE BLAZED AND SCRIBED "1/4 S 35 CS BT" BEARS WEST 62 ± FEET. THIS TREE HAS LOGS LYING AROUND BASE - BLAZE IS CENTERED APPROX. 2 FEET ABOVE GROUND.

3) SET AN ANGLE IRON FENCE POST 2 FEET WEST OF MONUMENT.

Location and Comments: 19° EAST. Compass Declination

DAUG. Co. SURV. OFF. Agency
LARRY E. MONREAN DEP. Party Chief

Larry E. Monrean Notekeeper
T.R. PLOUFF Witnesses

OK [Signature]