

DATE: Nov. 17, 1981

		T 24 S	
R		S 19	R
4	S 24		3
W		S 30	W

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal: #'s 1950 RESURVEY

Monument(s) Found: (Condition and Source) A 2 INCH DIAMETER

IRON PIPE WITH A BLM BRASS CAP ATTACHED, CAP IS

		T 24 S	"	T 24 S "
STAMPED	T 24 S	B S 19		
	R 4 W			
	S 24	S 30		
		R 3 W		
		1950		

MONUMENT PROTRUDES 1 FOOT ABOVE GROUND.

Accessories Found: (Condition and Source) _____

1) A FIR, 16 INCH DIAMETER, NOW A STUMP WITH SCAR VISIBLE
 IN GROWTH ^{RINGS} BEARS N 17 1/2° E 48 ⁸ FEET TO FACE 49 ⁷ FEET
 TO CENTER. THIS STUMP IS 20 INCH DIAMETER.

2) A FIR, 31 INCH DIAMETER, NOW A 31 INCH DIAMETER STUMP ABOUT
 5 FEET HIGH WITH PARTIALLY HEALED PITCHED OVER BLAZE
 BEARS S 57 1/2° E 6 ² FEET (RECORD 7 ³ FEET).

86 (T24-3) ✓
 # 160 (T24-4) ✓

C.S. File No. 61/29-24 Page _____ of _____
 C

3) NO OTHER BT'S FOUND SW BT DECAYED DURING 1950
RESURVEY, N W BT POSITION LOCATED IN NEWLY
LOGGED AREA.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) ¹⁾ SET BRIDGE SPIKE IN 48" DIA. RED CEDAR
STUMP, 2 FEET HIGH, SPIKE STAMPED "BD" BEARS S 13 1/2° E 14 6/8 FEET.

2) A W. FIR 9" DIA DOUBLE BLAZED AND SCRIBED "TASRAWSZACS BT" BEARS
N 9 1/2° W 8 2/8 FEET 3) A W. FIR 6" DIA. DOUBLE BLAZED AND SCRIBED

"S19CS BT" BEARS N 70° E 64 9/8 FEET. 4) A W. FIR 8" DIA DOUBLE
BLAZED AND SCRIBED "TASRAWS30CS BT" BEARS S 66° E 47 0/8 FEET

Location and Comments: 19° EAST Compass Declination
COENER LIES APPROX. 15' ± NORTH OF CUTTING LINE IN LOGGED AREA. DUG. Co. SURV. OFF. Agency
LARRY E. MONKEAN DEP. Party Chief
T.R. PLOUFF Notekeeper
Witnesses

OK [Signature]