

T28S R2W
1/4 S19
S30
1968
ORE 4906

DATE: NOV. 18, 1981

(TYPE
RENEW.)

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s 44,

Monument(s) Found: (Condition and Source) _____

1 1/2" d, I.P., FIRMLY SET, PROJECTING 14" ABOVE
GROUND, WITH BRASS CAP MARKED AS ABOVE, SET
BY BRUCE SHANER, REGISTERED PROFESSIONAL
ENGINEER #4906, IN 1968.

≠ ADD 2' d, MOUND OF STONE WITH I.P. NOW
PROJECTING 10".

Accessories Found: (Condition and Source) _____

BTs MARKED BY SHANER IN 1968:
A 12" YEWOD, S34°W, 24 1/2 FT., WITH SCRIBE MARKS
" 1/4 S 30 T 28 S R 2 W BT" VISIBLE ON PARTLY HEALED
BLAZE.

A 44" D. FIR STUMP, N7°W, 18° FT., WITH NO MARKS
VISIBLE.

#142 ✓

AND BT MARKED BY DONALD STONE, RLS # 835, IN
1977.

A 8" HEMLOCK, N84°W, 77' FT., WITH SCRIBE MARKS

(NOT REC. of)

"1/4 S19 BT" ~~WAS~~ AND BRASS WASHER STAMPED "RLS
835" VISIBLE ON PARTLY HEALED DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments:

Compass Declination

USFS

Agency

LEONARD HERZSTEIN

Party Chief

CORNER IS 75 FT.

Notekeeper

WEST OF USFS

JIM LANDRUM

Witnesses

ROAD # 2817,

AND ABOUT 180 FT.

NORTH OF STANDING TIMBER.

OK 