



DATE: APRIL 14, 1982

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 31,166

Monument(s) Found: (Condition and Source) \_\_\_\_\_

1 1/2" I.P. FIRMLY SET, PROJECTING 15" ABOVE  
GROUND, SET BY DOUGLAS COUNTY SURVEYOR'S  
OFFICE IN 1969, WITH BRASS CAP MARKED  
AS ABOVE. (#31)

Accessories Found: (Condition and Source) ORIG. BT.:

A 54" D. FIR, N23°E, 31° FT, WITH NO MARKS VISIBLE ON  
PREVIOUSLY OPENED BLAZE.

AND BTS MARKED BY COUNTY SURVEYOR'S OFFICE IN 1969:

A 10" W. FIR, <sup>(HEMLOCK, M79-48)</sup> N2°E, 21° FT., WITH HEALED DOUBLE BLAZE.

A 8" R. CEDAR, DOWNED, S50°E, 93° FT., WITH PARTIAL HEALED  
DOUBLE BLAZE FACE DOWN.

#1574

A 8" D. FIR, WEST,  $11^{\circ}$  FT., WITH HEALED DOUBLE BLAZE.

(HEMLOCK, M79-24) 1/8  
A 16" W. FIR, N  $16^{\circ}$  W,  $20^{\pm}$  FT., WITH HEALED DOUBLE BLAZE.

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

ADDED 3' DIAMETER MOUND OF STONE, FROM WHICH BRASS CAP AND I.P. NOW PROJECT 6"

New Accessories: (Description) \_\_\_\_\_

NEW BT MARKED:

A 10" R. CEDAR,  $565^{\circ}$  E,  $107^{\pm}$  FT., SCRIBED

"T27S R1W S17 CS BT"

Location and Comments:

CORNER IS ABOUT  
100' SOUTH OF  
LITTLE RIVER ON  
HIGH FLAT GROUND.

$17\frac{1}{2}^{\circ}$  E  
U.S.F.S.  
LEONARD HERSTEIN  
JIM LANDRUM

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

OK *[Signature]*