

T32S R3W

DATE: MAY 4, 1982



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s M49-69; M56-20

Monument(s) Found: (Condition and Source) _____

2 1/2 I.P., WITH BRASS CAP MARKED AS ABOVE,
FIRMLY SET, FLUSH WITH 1' d, MOUND OF
STONE. SET BY GLEN BAUGHMAN, REGISTER-
ED LAND SURVEYOR NO. 536, IN 1974.

Accessories Found: (Condition and Source) _____

BT MARKED BY BAUGHMAN IN 1974:

A 12" ~~A~~ HALF DEAD ALDER, ~~N~~ N68°E, 25 1/4 FT,
WITH SCRIBE MARKS "S 1/16 S22 BT" AND
BRASS WASHER ~~WAS~~ STAMPED "RLS 536"
VISIBLE ON PARTLY HEALED DOUBLE BLAZE.

A 8" HEMLOCK STUMP, N03 1/2°W, 26 9/16 FT. (REC.)

#218 X

N06°W, 26⁶ FT.) WITH SCRIBE MARKS "S¹/₁₆ SZX
BT" AND BRASS WASHER STAMPED "RLS 536"
VISIBLE ON PARTLY HEAVED BLAZE.
1" IRON ROD, BEARS N82°E, 43 FT., PROJECTING
8" ABOVE GROUND.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) I MARKED NEW BTS:

A 10" YEW, S28°E, 87 FT, SCRIBED "S¹/₁₆ SZZ
CS BT" ON DOUBLE BLAZE.

A 8" W. FIR, N79°4'W, 88' FT., SCRIBED "S¹/₁₆ SZI
CS BT" ON DOUBLE BLAZE.

SET 6 FT STEEL FENCE POST NORTH 2° FT WITH
USFS SIGNS #54-2 & #54-9 ATTACHED.

Location and Comments: 18'4" E Compass Declination

U S F S Agency

CORNER IS ABOUT JIM LANDRUM Party Chief

25 FT. WEST OF _____ Notekeeper

APPLEGATE CREEK LEONARD HERTZEN Witnesses

JIM HAMILTON

OK
JLM