

GOVERNMENT CORNER RESTORATION FORM

Township 27S Range 1W Sec. 8 County DOUGLAS

State OR. Date 6-7-82 No. _____

Corner Designation

T27S RIW

8 | 9

17 | 16

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals 1971 RESURVEY - #168

Monument(s) Found: (Condition and Source)

FD. 1971 BRASS CAP ON 2 1/2" IP
PROTRUDING 4" OUT OF GROUND
ON VERY STEEP, LOGGED OVER
SLOPE. BRASS CAP IS A STANDARD
BLM CAP STAMPED AS PER
DETAIL ON RIGHT

MONUMENT DETAIL

T27S RIW

S8 | S9

S17 | S16

1971

Accessories Found:

FD. 49" FIR PER RESURVEY, NOW 50" STUMP WHICH HAS
BEEN SPLIT OPEN, WITH SCRIBED "BT" VISIBLE IN PREVIOUSLY
OPENED FACE BEARS N 8° E 7 1/2 FT. (AS PER REC.)

FD. 38" FIR PER RESURVEY, NOW 38" STUMP WITH SCRIBED "RIW"
VISIBLE IN PREVIOUSLY OPENED FACE BEARS S 78° E 17 1/2 FT. (AS PER REC.)

FD. 12" HEMLOCK PER RESURVEY, NOW 12" STUMP WITH SCRIBED
"T27S RIW S8 BT" VISIBLE IN UNHEALED BLAZE BEARS N 73 W
109 1/2 (REC. PER RESURVEY N 70 W 106 1/2)

#188 ✓

G. L. B. No. 61/36-22

