

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

Reset Brass cap at $\frac{1}{4}$ cor. by using
 3 good distances and 2 orig. Bearing.
 By changing Quadrants on Renewal #111
 Everything F's.

SURVEYORS
 T305 R311
 COUNTY $\frac{1}{4}$ S1
 S12


RESET
 1983
 1963

New Accessories

Re Tagged Bearing Trees

Sketch of Monument, Accessories, and General Area

Location & Comments



This cor lies on South-East
 slope approx 140 Ft West
 of Draw

Comp. Declin. 19° E
 Agency DCSO
 Party Chief _____
 Notekeeper John M Powell
 Witnesses Randy Smith

Surveyor's Seal
 REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Larry E. Monrean
 OREGON
 JULY 13, 1979
 LARRY E. MONREAN
 #1830

T-30-3 5/4 COR SEC. 1

