

~~GOVERNMENT~~ CORNER RESTORATION FORM

Township 27S Range 2W Sec. 13 County DOUGLAS
State OREGON Date DEC. 12, 1984 No. _____

Corner Designation

NW 1/16 CORNER OF SECTION 13.

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out


Previous Renewals CS 61/32, M65-20

Monument(s) Found: (Condition and Source)

2 1/2" OUTSIDE DIAMETER IRON PIPE WITH BRASS CAP MARKED AS SHOWN, FIRMLY SET, FLUSH WITH GROUND, SET BY ROMANCO WARE, L.S. 1005, IN 1977.

A CONDITION REPORT BY JAMES LANDRUM, DEPUTY COUNTY SURVEYOR, IN 1982, FOUND WARE'S BT DISTANCES TO BE INCORRECT.

MONUMENT DETAIL



Accessories Found:

BTS MARKED BY WARE IN 1977:

A 14" D. FIR STUMP NO 2° E, 62 1/2 FT (REC. 63 1/2 FT.) WITH SCRIBE MARKS "BT" VISIBLE ON A PARTIALLY HEALED LOWER BLAZE.

A 10" HEMLOCK STUMP, S 83° W, 15 1/2 FT. (REC. ~~17~~ 17 1/2 FT.) WITH SCRIBE MARKS "NW 1/16 S13 BT" VISIBLE ON PARTIALLY HEALED DOUBLE BLAZE.

BOTH BTS HAVE A 1 1/2" DIAMETER ALUMINUM WASHER, ~~ATTACHED~~ STAMPED "LS 1005", NAILED TO LOWER BLAZE.

AND GUARD POSTS SET BY LANDRUM IN 1982:

A STEEL FENCE POST, EAST, 1 1/2 FT. (REC. 1 1/2 FT.) WITH USES SIGN #54-9 ATTACHED.

A STEEL FENCE POST, SOUTH, 1 1/2 FT. (REC. 1 1/2 FT.)

FILED
RECEIVED 2/8

20 1584
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

4

