

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 9W Sec. 26 County DOUGLAS

State OR Date 3/22/84 No. _____

Corner Designation

1/4 S23
S26

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1954 BLM DEP. RESURVEY, M96-20

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

1" I.P. WITH BRASS CAP PROTRUDING
6" ABOVE GROUND (1954 BLM DEP.
RESURVEY) MARKED AS NOTED.

U.S. GENERAL LAND OFFICE SURVEY

1/4 S23
S26
1954

Accessories Found:

NO ORIG. EVIDENCE FOUND

A 63 IN. FIR, NOW A 54 IN. STUMP 3 FT. HIGH WITH BURNT
SINGLE BLAZE AND PARTIAL SCRIBING VISIBLE BEARS N71°W,
26.0 FT. PER M96-20, (REC. N68 1/2°W, 15.8 FT PER 1954 BLM RESURVEY).

A 36 FIR, NOW A 30 IN. STUMP 4 FT HIGH WITH BURNT
SINGLE BLAZE AND SCRIBING VISIBLE "4S26BT" BEARS
S15°E, 28.6 FT PER M96-20 (REC S16°E, 23.1 FT) PER 1954 BLM RESURVEY.

#51 ✓

C.S. File No. 62/16-2-C

