

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 9W Sec. 26 County DOUGLAS

State OR Date 3/22/84 No. _____

Corner Designation

1/4 S27 | S26

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals 1953 BLM DEP. RESURVEY, 1967 BLM REN., M96-20

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

1" I.P. WITH BRASS CAP PROTRUDING 6" ABOVE GROUND (1953 BLM DEP. RESURVEY) MARKED AS NOTED.

U.S. GENERAL LAND OFFICE SURVEY

1/4
S27 | S26
1953

Accessories Found:

NO ORIG. EVIDENCE FOUND

A 10 IN. HEMLOCK NOW 18 IN. DIA. STUMP 20 IN. HIGH, WITH A WELL HEALED BLAZE BEARS N69°W 32.3 FT (31.0' PER M96-20 IS TO FACE). (PER 1953 BLM DEP. RESURVEY)

A 40 IN. FIR NOW A 33 IN. DIA. STUMP 7 FT HIGH WITH PROTECTIVE ALUM. SHEETING ON TOP, AND A VISIBLE SCAR SHOWING, BEARS S33°E 24.4 FT PER M96-20 (REC. S31 1/2°E) PER 1953 BLM DEP. RESURVEY.

#50 X

