

GOVERNMENT CORNER RESTORATION FORM

Township 27S Range 4W Sec. 15 County DOUGLAS

State OR Date 2/28/84 No. _____

Corner Designation

1/4 S16 | S15

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #39, #105

Monument(s) Found: (Condition and Source)

FOUND A IRON PIPE WITH BRASS CAP
PROTRUDING 12 IN. ABOVE GROUND,
PER REN # 39, MARKED AS NOTED.

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

T27S R4W
 1/4 S 16 | S 15
 1958

Accessories Found:

FD. ORIGINAL 10" NOW 20" ROTTED B. OAK SNAG 8 FT HIGH, NO BLAZE VISIBLE
BEARS N25°E, 13.0 FT (REC. 11.9 1ST FACE).

FD. 23" FIR NOW DEAD, PARTIALLY HEALED DOUBLEBLAZE WITH SCRIBING
VISIBLE "1/4 S15 CS BT", BEARS S76°E, 13.0 FT, PER. REN. #39.

FD. 20" NOW A 20" FIR STUMP 3 FT HIGH, NO BLAZE VISIBLE,
BEARS S76°W, 18.0 FT. PER. REN. #39.

FD. 19" NOW A 22" B. OAK SNAG 7 FT HIGH, SCRIBING VISIBLE "1/4 S15 CS BT"
BEARS N44°E, 38.5 FT. PER. REN #105.

FD. 25" B. OAK NOW A DEPRESSION IN GROUND, BEARS N23°W, 65.2 FT.
PER. REN. # 105.

NO EVIDENCE OF ORIG. 16" OAK WAS FOUND.

#143

C.S. File No. 62/16-11 C

