

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 9W Sec. 35 County DOUGLAS

State OR Date 7/4/89 No. \_\_\_\_\_

Corner Designation

1/4 S35

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1893 RESURVEY, 1954+1967 BLM RESURVEY M96-26

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

Ren # 54

A 1 IN. DIA. I.P. WITH A BRASS CAP  
PROTRUDING 4 IN. ABOVE GROUND  
(PER 1954 BLM RESURVEY) MARKED  
AS NOTED.

US GENERAL LAND OFFICE SURVEY

1/4 S35

1954

Accessories Found:

NO ORIG. EVIDENCE FOUND

NO EVIDENCE OF 1954 RESURVEY FOUND

67" NOW A 63" 3 FT HIGH FIR STUMP WITH SCRIBING VISIBLE "1/4 S 35 BT"  
BEARS N65°E, 78.5 FT (REC N62°E, 79.2') PER 1967 BLM RESURVEY.

20" NOW A 17" 4 FT HIGH MAPLE STUMP BEARS N58°W 26.6 FT  
PER M96-26 (REC. N58Y4°W, 25.7 FT) PER 1967 BLM RESURVEY.

#56

C.S. File No. 62/18-5

C

