

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 9W Sec. 35 County DOUGLAS

State OR Date 4/7/84 No. \_\_\_\_\_

Corner Designation

S35 | S36  
-----  
S2

- \_\_\_\_\_ Condition Report Only
- \_\_\_\_\_ Not Found
- Renewed
- \_\_\_\_\_ Unrecorded
- \_\_\_\_\_ Surveyed In
- \_\_\_\_\_ Referenced Out

Previous Renewals 1823 RESURVEY, 1954 BLM RESURVEY, 1967 BLM RESURVEY, M96-26

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

12 IN. DIA I.P. WITH BRASS CAP  
PROTRUDING 12 IN. ABOVE GROUND  
(PER 1954 BLM RESURVEY) MARKED  
AS NOTED.

US GENERAL LAND OFFICE SURVEY

T20S R9W

S35 | S36

T21S R9W

S2

1954

Accessories Found:

36" NOW A 38" BURNED AND ROTTED FIR STUMP BEARS N82°E, 153.5 FT  
PER M96-26 (RECORD N81 1/2°E, 153.1 FT PER 1967 BLM RESURVEY). ORIG.

36" NOW A 45" 4 FT HIGH FIR STUMP WITH A BURNED OUT CENTER BEARS  
S81°E, 118.0 FT. PER M96-26 (REC. S81 1/2°E, 116.8 FT PER 1967 BLM RESURVEY). ORIG.

NO OTHER ORIG. EVIDENCE FOUND

12" NOW A 13" HEMLOCK STUMP 1 1/2 FT HIGH WITH PARTIAL SCRIBING  
VISIBLE BEARS N14°W, 8.8 FT PER M96-26 (REC. N18°W, 9.2 FT PER 1967 BLM  
RESURVEY) PER 1954 BLM RESURVEY.

14" NOW A 18" HEMLOCK STUMP 1 FT HIGH WITH DOWNED BT, BT HAS SCRIBING  
VISIBLE "T20S R9W" BEARS N55°E, 22.1 FT PER M96-26 (REC. N53 1/2°E,  
21.8 FT PER 1967 BLM RESURVEY) PER 1954 BLM RESURVEY.

#55

C

