

GOVERNMENT CORNER RESTORATION FORM

Township 23S Range 7W Sec. 30 County DOUGLAS

State OR Date 5/30/84 No. \_\_\_\_\_

Corner Designation

S24 | S19  
S25 | S30

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals BLM DEPENDENT RESURVEYS IN

Monument(s) Found: (Condition and Source)

1964 AND 1979

MONUMENT DETAIL

2 1/2" IRON PIPE WITH BRASS CAP  
PROTRUDING 6" ABOVE GROUND  
(PER 1964 RESURVEY) MARKED AS  
NOTED

T 23 S  
R 8 W | R 7 W  
S 24 | S 19  
S 25 | S 30  
1964

Accessories Found:

A 18" NOW A 28" DIAM. D. FIR WITH A SINGLE HEALED BLAZE  
BEARS N 6° E, 268.0 FT. (PER 1964 RESURVEY).

A 37" NOW A 42" DIAM. D. FIR WITH A SINGLE HEALED BLAZE  
BEARS N 39° W, 376.9 FT. (PER 1964 RESURVEY).

A STEEL FENCE POST 6 FT LONG, SET 2 FT IN THE GROUND,  
IS ALONG SIDE EAST EDGE OF IRON PIPE. (PER 1964 RESURVEY).

A 1/2" REBAR 5 FT LONG, SET 2 FT IN THE GROUND, IS ALONG  
SIDE WEST EDGE OF IRON PIPE. (PROBABLY PER 1979 RESURVEY).

#131 T23-8 X  
#164 T23-9 X

