

GOVERNMENT CORNER RESTORATION FORM

Township 30S Range 5W Sec. 21 County DOUGLAS

State OREGON Date 6/7/84 No. _____

Corner Designation

N. E.
COR.
DLC
46

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals #266

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

1" I.P. WITH BRASS CAP (PER REN#266)
PROTRUDING 3" OUT OF A 1 FT DIAM
MOUND OF STONE.

DOUGLAS CO. SURVEYOR
T30S R5W

N. E. DLC
Cor. 46

1975

Accessories Found:

28" NOW 29" DIAM. PONDEROSA PINE WITH A SINGLE PARTIALLY
HEALED BLAZE (SCRIBING ILLEGIBLE), BEARS N 77 1/2° E, 118.0 FT
(PER REN#266).

A 5/8" I.R. WITH ALUMINUM CAP MARKED "DOUGLAS CO SURVEYOR
W.C. + " PROTRUDES 4" ABOVE THE GROUND, AT RECORD BEARING AND "
DISTANCE (S 2° 08' 36" W, 30.0 FT.) PER. REN#266.

A 5/8" I.R. WITH YELLOW PLASTIC CAP MARKED "DOUGLAS CO SURVEYOR"
PROTRUDES 6" ABOVE GROUND, AT RECORD BEARING AND DISTANCE (N 2° 08' 36" E, 40.46 FT.)
(PER. REN.#266). A METAL FENCE POST IS 4" WEST OF I.R. PROTRUDING 3 FT ABOVE
GROUND.

#3034

C.S. File No. 62/18-27 C

