

GOVERNMENT CORNER RESTORATION FORM

Township 28S Range 8W Sec. 16 County DOUGLAS

State OREGON Date AUG. 13, 1984 No. \_\_\_\_\_

Corner Designation

$\frac{1}{4}$   
S17 | S16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals BLM 1975 DEPENDENT RESURVEY

Monument(s) Found: (Condition and Source)

A  $3\frac{1}{4}$  INCH DIAMETER BLM DISK ATTACHED TO A  $2\frac{1}{4}$  INCH DIAMETER IRON PIPE PROTRUDING 6 INCHES FROM THE GROUND. CAP MARKED A INDICATED AT RIGHT.

U.S. DEPT. OF INTERIOR  
BUR. OF LAND MANAGEMENT  
T28S R8W

$\frac{1}{4}$   
S17 | S16  
1975

Accessories Found:

ORIGINAL BEARING TREES SEARCHED FOR NO EVIDENCE FOUND.

FROM THE 1975 BLM DEPENDENT RESURVEY TWO TREE FOUND. A W. FIR, 13 INCHES D. B. H. (RECORD A HEMLOCK, 8 INCH DIAM.) BEARS N55°E, 32.7 FEET. (RECORD N37°E 32.7 FEET) HAS WELL HEALED SINGLE BLAZE NO SCRIBING VISIBLE.

A D. FIR 21 INCHES D. B. H. (RECORD A FIR 17 INCH DIAM.) BEARS S82°W, 35.3 FEET (RECORD S63 $\frac{1}{2}$ °W, 36.3 FEET) HAS WELL HEALED SINGLE BLAZE NO SCRIBING VISIBLE.

\*NOTE: BLM NOTES INDICATE COMPA. BEARINGS DID NOT INCLUDE MAGNETIC DEVIATION.

1

#178 X

C.S. File No. 62/21-40 C

