

GOVERNMENT CORNER RESTORATION FORM

Township 26 S Range 3 W Sec. 9 County DOUGLAS

State OREGON Date 1-25-85 No. _____

Corner Designation

W P
S 9 | S 10

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1972 BLM RESURVEY

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

FD 1972 BLM IRON PIPE WITH BRASS CAP ATTACHED FIRMLY SET.

W P

S 9 | S 10

1972

Accessories Found: 1972 BLM BT'S

A FIR 10 NOW 13 INCHES DIAMETER

BEARS S 52° E 31 1/2 FEET (REC. S 56° E 31 1/2 FEET) TREE HAS PARTIALLY HEALED LOWER BLAZE WITH SOME SCRIBING VISIBLE, WELL HEALED UPPER BLAZE.

A FIR 8" NOW 10" WITH PARTIALLY HEALED BLAZE BEARS S 65° W 8 1/2 FEET (REC. 9 1/2 FEET)

