

GOVERNMENT CORNER RESTORATION FORM

Township 33S Range 5W Sec. 1 County DOUGLAS

State OR Date 1-15-85 No. \_\_\_\_\_

Corner Designation

S 2 | S 1  
C.C.  
T 33 S R 5 W

- \_\_\_\_\_ Condition Report Only
- \_\_\_\_\_ Not Found
- Renewed
- \_\_\_\_\_ Unrecorded
- \_\_\_\_\_ Surveyed In
- \_\_\_\_\_ Referenced Out

MONUMENT DETAIL

Previous Renewals REN #1, 1965 & 1970 BLM RESURVEYS

Monument(s) Found: (Condition and Source)

ORIG. POST AND 1 1/2" DIAM. PIPE ~~PER~~ PER REN. #1 NOT FOUND. (1965 BLM RESURVEY SET MONUMENT OVER PIPE).

FOUND IRON POST AND BRASS CAP MONUMENT FROM 1965 BLM RESURVEY, FIRMLY SET AND PROTRUDING 8" ABOVE GROUND.

T 32 S

S 35  
S 2 | S 1  
T 33 S CC E 5 W  
1965

Accessories Found:

- ORIGINAL 12" FIR NOW A 36" DIAM STUMP WITH VISIBLE SCRIBING "33S R 5WCC" IN OPENED BLAZE BEARS N 85° E 35.2 FEET.
- POSSIBLE ORIGINAL BT CALLED BY 1965 RESURVEY AN 18" DECAYED FIR STUMP WITH CHOP AND SAW EVIDENCE TO THE CENTER, NO SCRIBING OR BLAZE VISIBLE. BLM RESURVEY CALLS BEARING S 34° E 41 LKS. FAILS AT WEST EDGE OF GRAVEL ROAD. ORIGINAL BEARING AND DISTANCE S 44° E 41 LKS FAILS IN TRAVELED ROADWAY. WE MEASURE S 35 1/2° E 26.9 FEET.
- NO OTHER ORIG. BTS FOUND
- FROM RENEWAL #1 NOT CALLED IN BLM RESURVEYS A 12" FIR NOW 34" DIAM WITH PITCHED OVER SINGLE BLAZE BEARS S 32° W 30.4 FEET. TREE IS AT RANDOM FENCE CORNER, TOP HAS BEEN CUT OUT AT ABOUT 30 FEET HIGH (HEALTHY AND GROWING).
- FROM 1965 BLM RESURVEY A 12" FIR NOW 21" DIAM. WITH WELL HEALED SINGLE BLAZE BEARS S 14° E 20.8 FEET.

#38 ✓

