

GOVERNMENT CORNER RESTORATION FORM

Township 27S Range 3W Sec. 11 County DOUGLAS

State OR Date 7/9/85 No. \_\_\_\_\_

Corner Designation

$\frac{1}{4}$   $\frac{S11}{S14}$

- \_\_\_\_\_ Condition Report Only
- \_\_\_\_\_ Not Found
- Renewed
- \_\_\_\_\_ Unrecorded
- \_\_\_\_\_ Surveyed In
- \_\_\_\_\_ Referenced Out

Previous Renewals #1, 1984 BLM UNOFFICIAL RESURVEY COPY ATTACHED

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)  
A BLM DISK ON A 2" DIA I.P.  
PROTRUDING 7 IN. ABOVE GROUND,  
MARKED AS NOTED, WITH A 3/4" INSIDE  
DIA I.P. ALONG WEST EDGE OF DISK  
PROTRUDING 9 IN. ABOVE GROUND PER REN#1  
AND A 5/8" I.P. ALONG NORTHWEST EDGE  
OF DISK PROTRUDING 5" ABOVE GROUND  
SOURCE UNKNOWN.

US DEPT. OF THE INTERIOR  
 T27S R3W  
 $\frac{1}{4}$   $\frac{S11}{S14}$   
 1984  
 BUR. OF LAND MANAGEMENT

Accessories Found:

ORIGINAL BT'S

16" NOW A 40" DIA R. CEDAR WITH A CHOPPED INTO PARTIALLY  
HEALED UPPER BLAZE SCRIBE VISIBLE "S", LOWER BLAZE IS PARTIALLY  
HEALED WITH POSSIBLE SCRIBING VISIBLE BEARS S43°W, 31.7 FT  
(REC. S25°W, 31.7 FT).

18" NOW A 46" DIA R. CEDAR WITH A CHOPPED INTO UPPER  
BLAZE NO SCRIBE VISIBLE, LOWER BLAZE IS PARTIALLY HEALED  
WITH SCRIBING VISIBLE "CS BT" BEARS N61°W, 12.2 FT  
(REC. N45°W, 9.2 FT DIST IS A FACE MEASUREMENT).



RANDY  
OF THE

COUNTY SURVEYORS OFFICE

Dependent Resurvey of a Portion of the Subdivisional  
Lines, T. 27 S., R. 3 W., Willamette Meridian, Oregon

CHAINS  
20.89

The  $\frac{1}{4}$  sec. cor. of secs. 11 and 14, perpetuated and recorded by Ben Irving, County Surveyor, in 1945, monumented with a 1 in. iron pipe, projecting 8 ins. above the ground.

from which the remaining original bearing trees

A cedar, 41 ins. diam., bears S.  $41\frac{1}{2}^{\circ}$  W., 48 lks. dist., with fragmentary scribe marks on opened blaze. (Record, bearing: S.  $25^{\circ}$  W.)

A cedar, 53 ins. diam., bears N.  $61\frac{1}{2}^{\circ}$  W., 18 lks. dist., with fragmentary scribe marks on opened blaze. (Record, bearing: N.  $45^{\circ}$  W.)

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T27S R3W  
 $\frac{1}{4}$  S11  
S14  
1984

Deposit the iron pipe alongside the iron post.

Cor. is located at intersection of fences extending N., S., and E.

S.  $88^{\circ} 05'$  W., beginning new measurement.

Ascend over broken NE. slope.

42.09

The cor. of secs. 10, 11, 14, and 15, monumented with an iron post,  $2\frac{1}{2}$  ins. diam., firmly set, projecting 3 ins. above ground, with brass cap mkd.

T27S R3W  
S10|S11  
S15|S14  
1958

from which the remaining original bearing trees

A fir, 30 ins. diam., bears S.  $68^{\circ}$  E., 19 lks. dist., with healed blaze.

A roothole, with downed fir alongside, 44 ins. diam., bears N.  $38^{\circ}$  W., 54 lks. dist., no marks visible.