

GOVERNMENT CORNER RESTORATION FORM

Township 29S Range 5W Sec. 32 County DOUGLAS

State OR Date 10/10/85 No. _____

Corner Designation

DLC
42

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals # 197

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

AN ORIGINAL STONE FIRST NOTED IN THE ORIGINAL SURVEY OF DLC #43 AND FIRST DESCRIBED AS A 12" x 16" STONE, MARKED DLC 42, IN THE UNRECORDED GRAY ACRES PLAT, CS 50/56, IS NOW A BROKEN BUT FIRMLY SET STONE, MARKED AS AT RIGHT AND MEASURING 8" x 8" x 14".

SCRIBED ON TOP OF STONE

42 (TOP PORTION OF 2 BROKEN AWAY NOT FOUND)

Accessories Found:

FROM THE UNRECORDED GRAY ACRES PLAT, CS 50/56, A 3/4" IRON PIPE FIRMLY SET BUT LEANING SOUTHWESTERLY BEARS NORTH APPROX 13 FT. DIST (RECORD NORTH 15 FT.). ALSO FROM CS 50/56 A 3/4" IRON PIPE FIRMLY SET BUT LEANING SOUTH. AT ITS PLUMB POSITION IT BEARS NORTH, 110 2/3 FT. DIST. (AS PER RECORD)

FROM THE B.B. IRVING SURVEY M 9-43 A 3/4" x 3/4" ANGLE IRON FIRMLY SET AND PROTRUDING 6 INCHES FROM THE GROUND BEARS WEST, 22.6 2/3 FT DIST (REC 589°57'W, 22.7 2/3 FT)

FROM RENEWAL #197 A DCSO BRASS CAP ON AN IRON PIPE SET FLUSH WITH GROUND BEARS SOUTH, 92.9 FT. DIST. (AS PER RECORD)

#221X

