

GOVERNMENT CORNER RESTORATION FORM

Township 31S Range 5W Sec. 23 County DOUGLAS

State OR Date 10/28/85 No. _____

Corner Designation

523	524
526	525

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1973 DEP. RESURVEY

Monument(s) Found: (Condition and Source)

A BLM DISK SET FLUSH IN CONCRETE
OF OLD ABANDONED HWY 99 ROAD
SURFACE. MARKED AS NOTED

US GENERAL LAND OFFICE SURVEY

T31S R5W

523	524
526	525

1973

Accessories Found:

BT'S PER 1973 DEP. RESURVEY

A 17" NOW 18" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE
BEARS N12°E, 63.8 FT. (REC. N15°E, 62.7 FT.) SLOPE FACE MEASUREMENT RWS

A 10" NOW 16" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE
BEARS S55°E, 66.6 FT. (REC. S55°E 67.3 FT. SLOPE MEASURE)

A 13" NOW 18" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE
BEARS S22°W 68.4 FT (AGREES WITH REC.)

A 19" NOW 22" DIA. D. FIR WITH A FULLY HEALED SINGLE BLAZE
BEARS N60°W, 80.0 FT (REC. N60°W, 81.5 FT.) FACE MEASUREMENT)

#115+

