

GOVERNMENT CORNER RESTORATION FORM

Township 25S Range 1E Sec. 30 County DOUGLAS

State OR Date 4/8/86 No. _____

Corner Designation

$\frac{1}{4}$ $\frac{S30}{S31}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #23

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A GLO BRASS CAP ON AN I.P.
PROTRUDING 11 IN. ABOVE GROUND
(ORIG.)

U.S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4}$ $\frac{S30}{S31}$
1927

Accessories Found:

18" NOW 24" DIA. 6 FT HIGH FALLEN D.FIR STUMP WITH A FULLY
HEALED SINGLE BLAZE BEARS S48°W, 23.8 FT (AGREES WELL
WITH REC.) ORIG. BT.

10" NOW 16" DIA. 2 FT. HIGH DECAYED HEMLOCK STUMP WITH A PARTIALLY
HEALED BLAZE, SCRIBING VISIBLE "S 30 BT" BEARS N10 1/2° W
33.0 FT (AGREES WELL WITH REC.) ORIG. BT.

6" NOW 10" DIA. CHINQUAPIN WITH A PARTIALLY HEALED DOUBLE
BLAZE NO SCRIBING VISIBLE BEARS N26°E 69.4 FT
(REC. N26°E, 68.7 DIST. TO CENTER OF TRUNK) PER REN #23

