

GOVERNMENT CORNER RESTORATION FORM

Township 28S Range 7W Sec. 31 County DOUGLAS

State OR Date 6/15/87 No. _____

Corner Designation

TR 63
AP5
NW COR
DLC 56
AP2

- ? Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #38, 1924 GLO RETRACEMENT

Monument(s) Found: (Condition and Source)

A 1924 GLO 1 IN. I.P. WITH BRASS CAP
PROTRUDING 1/2 IN ABOVE GROUND. TOP OF
BC/UP. IS BENT 3 IN SOUTH OF PLUMB
POSITION.

A 5" WIDE BY 3/8" THICK IRON BAR
1 INCH BELOW GROUND FOUND ALONG
NORTH EAST EDGE OF BC/UP. (POSSIBLE
IRON BAR SET PER REN. #38)

1" IRON PIPE FOUND BY GLO IN 1924
WAS LOOKED FOR BUT NOT FOUND.

Accessories Found:

BEARINGS AND DISTANCES TAKEN TO PLUMB POSITION OF 1924 GLO BC/UP.
30" NOW 38" DIA. B. OAK, WITH A FULLY HEALED DOUBLE BLAZE,
BEARS S 1 1/2° E, 85.1 FT (REC. S 1 1/2° E, 84.2 FT IS A POSSIBLE FACE MEASUREMENT).
PER REN # 38.

30" NOW 77" DIA. 5 FT HIGH ROTTED PINE STUMP, NO BLAZES OR
SCRIBING FOUND, BEARS N 42 1/2° W, 96.0 FT (REC. N 42 1/2° W, 94.8 FT
IS A POSSIBLE FACE MEASUREMENT). PER REN #38.

10" NOW 14" DIA. N. OAK WITH A FULLY HEALED SINGLE BLAZE,
BEARS N 23 1/2° E, 80.5 FT (AGREES WITH REC.) 1924 GLO RETRACEMENT.

10" NOW 15" DIA. W. OAK WITH A FULLY HEALED SINGLE BLAZE,
BEARS S 40 1/2° E, 77.8 FT (REC. S 40 1/2° E, 76.6 FT A POSSIBLE
FACE MEASUREMENT). 1924 GLO RETRACEMENT.

MONUMENT DETAIL

U.S. GENERAL LAND OFFICE SURVEY

TR 63

AP5
AP2
DLC 56

1924

#263 ✓

