

GOVERNMENT CORNER RESTORATION FORM

Township 20S Range 12W Sec. 10 County DOUGLAS

State OR Date 10/4/88 No. _____

Corner Designation 2" IRON PIPE DESIGNATED AS

$\frac{1}{4} \frac{S10}{S15}$

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals #90

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2" O.D. IRON PIPE, RUSTED AND TOP BROKEN, PROTRUDES 2 IN. ABOVE GROUND PER REN #90

N/A

Accessories Found:

24" NOW 32" DIA 3 FT HIGH BURNT SPRUCE STUMP, WE OPEN NO SCRIBING OR BLAZES FOUND, NAIL WAS FOUND ALONG EAST SIDE OF STUMP. BEARS N21°W, 15.8 FT (ORIG. REC. N14°W, 15.2 FT)

26" DIA. SPRUCE NOW A 30" DIA. 4 FT HIGH BURNT D. FIR STUMP OCCUPIES POSITION. POSSIBLE OPEN BLAZE WITH AXE MARKS, NO SCRIBING FOUND BEARS S65°E, 13.8 FT (ORIG. REC. S65°E 13.7 FT)

24" NOW 24" DIA. 3 1/2 FT HIGH D. FIR STUMP WITH A POSSIBLE OPEN FACE NO MARKS SEEN, BEARS N70 1/2°E, 25.5 FT. (REC. N70 1/2°E, 24.9 FT DISTANCE IS A POSSIBLE FACE MEASUREMENT). PER REN #90

#1134

9-12-88

Fritz

I found an apparent $\frac{1}{2}$ corner for

$\frac{10}{15}$ T 20 S R 12 W. Saturday. a very old
Iron pipe and two tags. I did not
have GCU notes so I could not look for
old BT's. We will be logging the area
in 30 to 60 days. If you wish to
preserve the corner I would be glad
to show your crew its location

Bob Crain
Murphy Sales
997-8455

10:45
[Faint handwritten notes]

