

FILED

Handwritten initials

JUN 8 1987

OREGON CORNER RESTORATION FORM

Section 18/17 19/20 Township 31S Range 8W

County Douglas Date June 4, 1987

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1967 County Renewal # 36 1975 CAD Resurvey

Monument(s) & Accessories Found: (Condition and Source)

- 38" DF N 39E 57 1/2 OBT - STUMP.
- 24" DF S 66E 9 1/2 OBT shows scar OK
- 39" DF S 58W 19 1/2 OBT STUMP
- 12" Cedar N 8W 26 1/2 Gone
- 7" White N 35E 15 1/2 Gone
- 9" Hem S 46W 37 1/2 Gone

Pen # 36 BT

B.C. had been pulled out of ground from logging

Monument Detail

Sketch



Monument Set (Procedures and Description)

Reset Brass Cap at record distances from remaining BT and the OBT stumps.

New Accessories

- OBT 44" DF Stump S 58W 20 1/2 Alum Nail in top of stump, scribed.
- 5" Hemlock N 18E 45 1/2 scribed T31S RBW 517 BT with Tag
- 10" Hemlock N 75W 85 1/2 scribed T31S RBW 518 BT with Tag
- 6" Hemlock S 32E 22 1/2 scribed T31S RBW 520 BT with Tag

Location & Comments

All timber around Cor Compass Declination 20°
has been cut except in Firm/Agency Roseburg
Sec. 20. Resources
Cor. is on NW slope Address P.O. Box 1098
400' below access Roseburg
road. 31-8-20 Party Chief Howard Johnstone

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Howard W. Johnstone

OREGON
MAY 13, 1980
HOWARD W. JOHNSTONE
498

Notes

Witness

#81X