

TOWNSHIP 32 SOUTH

RANGE 2 WEST

FIRST RE-ESTABLISHMENT

Section corner common to Sections 20, 21, 28 & 29, Township 32 South, Range 2 West, W.M.

Fd. 2 ins. diam. galvanized iron pipe, projecting 10 ins. with 3 ins. diam. brass cap mkd:

T32SR2W
S20 | S21

S29 | S28
1968
OLS 536

as recorded on Survey No. 3822, dated 1968.

The single remaining original bearing tree, mkd. by C. Campbell in 1902, a douglas fir, now 54 ins. diam., containing scribe mks. including "S, 2 & W" in partly exposed face, brs. record; S73°W, 25.08 ft. to center of tree at base. Note: The original stone could not be found.

Bearing trees mkd. on the above noted survey:

Douglas Fir, 32 ins. diam., with healed blazes, brs. N30°E, 67.95 ft. to center of tree at lower blaze. Record; 66.8 ft.

White Fir, 9 ins. diam., with healed blazes, brs. N79°W, 11.95 ft. to center of tree at lower blaze. Record; 11.5 ft.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

White Fir, 9 ins. diam., brs. S36°E, 15.70 ft.

Douglas Fir, 7 ins. diam., brs. S46½°W, 22.10 ft.

Corner lies about 150 ft. S25°E of old Richter cabin.

September 7, 1988
R. Frost, Tech.
S. Beecher, Tech.

Edward McGinty
County Surveyor

FILED

V=18°

p-350 JAN 20 1989

FIRST RE-ESTABLISHMENT

Quarter corner on the West line of Section 30 only, Township 32 South, Range 2 West, W.M.

Fd. projecting 10 ins. in ring of stone, the 2 ins. diam. galvanized iron pipe with 2½ ins. diam. brass cap mkd:

T32S R2W
½ S 30
PLS 866
1980

set on Survey No. ~~8437~~, dated 1980.

An original bearing tree mkd. by C. Campbell in 1902, now a (sawed) madrone stump, 18 ins. diam., containing (partial) scribed "3" & "BT" in rotted face, brs. N3°E, 27.41 ft. to center of stump. Record; N1½°E, 29.70 ft.

An original bearing tree, subsequently relegated to a "former bearing tree" on a 1913 G.L.O. resurvey; now a burnt fir snag, 48 ins. diam., containing old axe work, brs. S15½°W, 47.63 ft. to center of tree. Record; S17°W, *50.16 ft.

The original stone could not be found, nor the yew bearing tree reported in 1913.

As all trees in the vicinity of the corner have been destroyed by recent (1987) forest fir; set references as follows:

Rebars 5/8 ins. by 24 ins., set 22 ins. in the ground, with yellow plastic caps mkd. "Jackson C.S." br.:

1. N66°E, 8.19 ft.
2. S50°E, 6.45 ft., located at the base of a 48 ins. diam. fir stump.

Corner lies on steep (65%) Southwest slope, about 225 ft. Southwest of road.

*See Jackson County project file 88-63.

November 3, 1988
R. Frost, Tech. & H. Durkee

Edward McGinty
County Surveyor

V=18°
p-377

C.S. File No. 63/82-10

#13/T32-2 +
#233 T32-3 +

#10/T32-3

M 84-6 REN #118