

FILED

JAN 27 1989

OREGON CORNER RESTORATION FORM

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Section 21 Township 235 Range 4W

County Douglas Date Oct. 12, '88

Corner Designation

1/4 S 21 1/2 22

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

See Survey by Shaner, 1974, CS Map File M49-55

Monument(s) & Accessories Found: (Condition and Source)

Fd Brass Cap Set by Shaner from which:  
18" D. Fir BT, face overgrown, Bears N58°W, 52 1/2 ft.

~~Right Power Pole, Str~~  
For Replacement PPL Poles, see below in  
"New Accessories"

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Right Power Pole, Structure R-16, PPL Pole No. 28050,  
bears S76°E, 32.7 Ft.

Left Power Pole, Structure No 1/76, PPL Pole No.  
28043, bears S62°E, 49.5 feet.

Location & Comments

Surveyor's Seal

Compass Declination \_\_\_\_\_

Firm/Agency \_\_\_\_\_

Address \_\_\_\_\_

Party Chief \_\_\_\_\_

Notes \_\_\_\_\_

Witness \_\_\_\_\_

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*BA Shaner*

OREGON  
OCT. 4, 1987  
BRUCE A SHANER  
420

C.S. File No. 63/85-7

#1814