

FILED *JH*

OREGON CORNER RESTORATION FORM

Section 26 Township 31S Range 7W

MAY 22 1989

County Douglas Date May 19, 1989

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

Corner Designation

1/4 COR 27/26

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. Renewal No. 25  
1964 Cadastral Resurvey

Monument(s) & Accessories Found: (Condition and Source)  
26" D.F. N 2 1/2 W 21° Healed Face, good Condition # 25  
No evidence of any other Bts of record.

B.C. and I.P. had been dug out during fire trail construction

Monument Detail

Sketch



Monument Set (Procedures and Description)

Reset the I.P. and B.C. in their proper location  
from the remaining D.F. Bt.

New Accessories

8" Chinkapin S 10° W 38 1/2 scibed " 1/4 S 27 BT "  
No trees available to scibed in Sec 26 as it has been  
recently clear cut.

Location & Comments

Surveyor's Seal

Compass Declination 20°  
 Firm/Agency Roseburg Resources Co.  
 Address P.O. Box 1098  
Roseburg, OR  
 Party Chief Howard W. Johnstone  
 Notes \_\_\_\_\_  
 Witness \_\_\_\_\_

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Howard W. Johnstone*  
OREGON  
MAY 13, 1989  
HOWARD W. JOHNSTONE  
498

#1204

C.S. File No 63/95-1