

FILED

JH
SEP 14 1989

OREGON CORNER RESTORATION FORM

Section 35 Township 30S Range 9W

County Douglas Date 9/8/89

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

S 1/16 between Sections 34/35

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Cor. Set By BHW Engineering + Surveying Jan. 1980
C/S File M 79-18

Monument(s) & Accessories Found: (Condition and Source)

5/8" IR with Aluminum Cap good condition

10" Fir S56W 33I now a stump.

20" Fir N30E 21I now a stump.

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

6" Chinkapin S74W 32E scribed "S 1/16 S 35 BT" Tag LS 498

9 W Fir S10W 21E scribed "S 1/16 S 35 BT" Tag LS 498

Location & Comments

Corner lies below Compass Declination _____

Spur road in recent Firm/Agency Roseburg

clear cut unit Forest Products _____

Address P.O. Box 1088

Roseburg, OR

Party Chief H W Johnstone

Notes _____

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
MAY 13, 1960
HOWARD W. JOHNSTONE
498