

FILED JP

OREGON CORNER RESTORATION FORM

AUG 4 1993

Section 29 Township 31S Range 5W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date July 20, '93

Corner Designation

1 29
4 32

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

T.R. Eslinger renewed corner in 1950.
Douglas County Surveyor " " " 1966 (Powell).

Monument(s) & Accessories Found: (Condition and Source)

Found 2 each 1 1/4" Iron Rods at corner. One is an Axle,
40" long as per 1950 record, and from which a:
24" D. Fir BT Stump, well decayed, bears S6°W, 15 3/4 feet.
10" White Fir BT (record 3"), face overgrown, bears S21°W,
20 3/4 feet.
10" White Fir BT (record 3"), face overgrown, bears
N78°W, 11 3/4 feet.

Monument Detail

Sketch

As above.

Monument Set (Procedures and Description)

None.

New Accessories

I set a 6 foot long steel fence post alongside corner's
iron rods.
I set a " " " " " " West of corner,
34 1/2 feet, on the easterly R/W line of the Gas Trans-
mission line.

Location & Comments

The logging road, Compass Declination 20 1/2° E
running East & West, Firm/Agency
crosses the Gas Shaner Engineering, Inc
line about 300 Address P.O. Box 1430
feet South of Roseburg Oregon 97470
1/4 corner. Party Chief B. Shaner
Notes " "
Witness Jack Wright

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Expires Dec. 31, 1994

C.S. File No. 63/153-28