

OREGON CORNER RESTORATION FORM

SEP 2 1993

Section 16 Township 295 Range 4W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date Aug. 28, '93

Corner Designation

16	15
21	22

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

U.S.B.L.M., 1969

Monument(s) & Accessories Found: (Condition and Source)

Found Brass Cap, 3/4" on 2 1/2" Diam. Iron Post, from which a:
7" Cedar BT, bearing N 71 3/4° E, 19.1 feet, destroyed & gone.
25" Cedar BT Stump, scribes visible, bears S 26° E, 38.0 feet.
28" D. Fir BT, face overgrown, bears S 36 1/4° W, 70.0 feet.
55" D. Fir BT, bearing N 21 1/4° W, 77.9 feet, now gone.

Monument Detail

Sketch



Monument Set (Procedures and Description)

None.

New Accessories

10" Cedar BT, I scribed "T295, R4W, S15 BT" bears ^{3/15 feet} N 83° E,
16" Cedar BT, I scribed "T295, R4W, S22, BT" bears S 64° E, 8.0 feet.
8" Pine BT, I scribed "T295, R4W, S16, BT" bears N 30° W, 37.4 feet.

Location & Comments

Corner located at
Newer fence corner.
Fence bears North
& East.

Compass Declination 20° E
 Firm/Agency Shaner
Engineering, Inc.
 Address P.O. Box 1430
Roseburg, Oregon
 Party Chief B. Shaner
 Notes " "
 Witness Do Stone

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Expires Dec. 31, '94.

G.S. File No. 63/153 26