

M 112-75

Filed
June 17, 1993

OREGON CORNER RESTORATION FORM

Section 16 Township 27S Range 6W

County Douglas Date June 14, 1993

Corner Designation

SW Corner of Wrd McKinney
D.L.C. No. 50

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals/Surveys, etc.

Ben B. Irving, Survey of County Road No. 13, April 1, 1928
Roger Bee, Shows Tie to Corner, Survey Map M32-42, Nov. 1966

Monument(s) & Accessories Found: (Condition and Source)

Found Rock, Top is 4" x 5" x 2", buried in ground (est. length 18")
& from which rock a:

16" White Oak BT Stump, badly rotten with reverse scribes
showing near stump center, bears N43°E, 40 2/3 feet.
(Was originally 8" Black Oak in 1928).

14" White Oak BT, face shows axe mark but is now
overgrown (I did not open), bears N70°E, 43 1/2 feet.
(Was 8" White Oak in 1928).

Monument Detail

Sketch

As above,

Monument Set (Procedures and Description) - None, Used Rock

I set 2 each steel fence posts; one at due West,
12 feet and one at due North, 12 feet.

Also, from corner rock, a 10" White Oak BT, I
scribed "SWC CL50 BT", bears N48°E, 45 2/3 feet.

New Accessories

Location & Comments

Corner is N45°W,
approx. 300 feet
from the Denzer
residence at
641 San Souci Drive.

Compass Declination 20°E
Firm/Agency Shaner
Engineering
Address P.O. Box 1430
Roseburg, Oregon 97470
Party Chief B. Shaner
Notes " "
Witness C. Berlier

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Expires Dec 31, '94