

Date: 12/29/94 By: JPH

OREGON CORNER RESTORATION FORM

This survey consists of:
Map: _____
Narrative: _____
Corner rpt: C563/154

Section 33 Township 22S Range 8W

County Douglas Date 10/14/94

DOUGLAS COUNTY
SURVEYOR

Corner Designation

South-west corner of DLC 54

Condition Report Only
Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals/Surveys, etc.

Monument(s) & Accessories Found: (Condition and Source)

Found BLM 2 1/2 inch brass cap on one inch iron pipe buried in mud of the washed out bank on the stream, rotten Hemlock stump remains (original corner) washed out down stream.

Monument Detail

Sketch

T22S R8W

S33 C54

1964

Monument Set (Procedures and Description)

We reset monument by distances given in the 1964 corner notes of the bearing trees for the corner
46' Western Red cedar bears N10°E, 93.7 feet (Record N9°E, 93.72 feet)
25' Douglas fir bears S74°30'E, 52.1 feet (Record S74°30'E, 52.14 feet), BLM Tag, healed scar
28' Western Red cedar bears N49°30'E, 74.3 (Record N48°E, 74.58 feet), BLM Tag, healed scar

New Accessories

We tagged 46" Western Red cedar. We painted faces and painted "BT" on trees.

Location & Comments

Corner lies in the bottom of a small creek bed the creek lies in a steep North-South ravine

Compass Declination N19 1/4°E
Firm/Agency Lone Rock Timber Co.
Address P.O. Box 1127
Roseburg, Oregon 97470
Party Chief Ken Hoffine
Notes _____
Witness Jerry Ragon

Surveyor's Seal



exp. date
6-30-95