

FILED

Date: 12/29/94 By: JP

This survey consists of:

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: C.S. 63/154

OREGON CORNER RESTORATION FORM

Section 31 Township 24S Range 6W

County Douglas Date 10/24/94

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

30  
31

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1967 Dependent Resurvey by Wm. Raspberry

Monument(s) & Accessories Found: (Condition and Source)

1967 BLM Brass Cap & Iron Pipe

BTs: 25" Fir N50°W 22<sup>±</sup>' Rotten Stump OBT (1853)

39" Fir N23°E 24<sup>±</sup>' Burnt Stump OBT (1853)

31" Fir S3°E 23<sup>±</sup>' Stump OBT (1853)

16" Fir S68°E 72<sup>±</sup>' Healed 1967 BLM

47" Fir N35<sup>3</sup>/<sub>4</sub>°W 9<sup>±</sup>' Healed 1984 IP

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 20°

Firm/Agency Roseburg

Forest Products

Address P.O. Box 1088

Roseburg, Oregon

Party Chief F. White

Notes W. Olson

Witness R. McManis

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Mark F. Smalley  
OREGON  
JULY 26, 1988  
MARK F. SMALLEY  
2354

EXP. 12/31/94

C.S. File No. 63/154 (24)