

M 121-52

FILED

Date: 2/16/95 By: JC
This survey consists of:
Map: M 121-52
Narrative: _____
Corner Rpt: CS 63/161

OREGON CORNER RESTORATION FORM

Section 34 Township 26S Range 3W

County Douglas Date Feb. 3, '95

DOUGLAS COUNTY
SURVEYOR

Corner Designation

CS 1/16 Sec. 34

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Survey by McKind in 1973, County Surveyors Map File M5T-34

Monument(s) & Accessories Found: (Condition and Source)

5/8 inch iron rod, at fence corner bearing North and East. From said 5/8" Iron Rod a 32" Cedar BT (record 25"), scribes visible, bears S14°W, 35.6 feet.

Monument Detail

Sketch

N/A

Monument Set (Procedures and Description)

N/A

New Accessories

12" D. Fir BT, I scribed "CS 1/16 S34 BT," bears N54°E, 74' feet.

Location & Comments

Corner is about 200 feet South of "Old Cabin Road".

Compass Declination 21°E

Firm/Agency Shaner Engineering, Inc.

Address P.O. Box 1430 Roseburg, Oregon 97470

Party Chief B. Shaner

Notes " "

Witness Jack Wright

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Bruce A. Shaner

OREGON
OCT. 4, 1957
BRUCE A. SHANER
430

Expires June 30, '96

C.S. File No. 63/161-3